



photo 1: Facing south toward the location.



photo 2: Well sign at the location.



photo 3: Facing toward the wellhead.



photo 4: Water was leaking from the wellhead.



photo 5: A barrel labeled Clarient Oil service was tip over.



photo 6: Facing east toward the wellhead.