

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2017

Submitted Date:

02/06/2017

Document Number:

667600120**FIELD INSPECTION FORM**
 Loc ID 320217 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: UNIT E 2121 39TH AVENUE NECity: CALGARY State: AB Zip: T2E 6R7**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Conn, Lionel	1 40 3250 7225	tudorcorp@hotmail.ca	President
Reeve, Robert	360-683-3385	rrobert169@qwest.net	Engineer
MCCLANE, GENE		genemcclane@hotmail.com	All inspections
Rutter, Jenn		JRutter@adcogov.com	Unincrop. Adams County Inspections.

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203084	WELL	PR	12/01/2014	OW	001-08491	LAMBERT 2	WK

**General Comment:**

Spoke with Gene McClane on workover location, he is currently in process of taking ownership of well and location from Tudex.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Signage at battery lacks emergency contact information.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign reflects Tudex		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	No emergency contact information posted at battery.	
Corrective Action:	Install sign to comply with Rule 210.b.	Date: 03/07/2014

**Good Housekeeping:**

Type		
Comment:	No trash and debris as indicated by previous inspection.	
Corrective Action:		Date:

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Separator	<= 1 bbl	
Comment:	Stained soil below fire tube at separator. See attached photos.		
Corrective Action:	Remove or remediate stained soil.		Date: 03/06/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Paint on separator is not proper coloring.		
Corrective Action:	Paint separator per Rule 804.		Date: 07/01/2017
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	Gas fired engine.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		,

Comment:	Fiberglass open top, netting needs repaired, see attached photos.	
Corrective Action:	Repair netting to mitigate possible wildlife entry.	Date: 04/06/2017

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Same berms as oil tank.	
Corrective Action:		Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,

Comment:	Tank paint in not proper coloring. See attached photos.	
Corrective Action:	Paint tanks per Rule 804.	Date: 07/01/2017

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate

Comment:	An animal burrow south east corner of tank berm. See attached photos.	
Corrective Action:	Repair berms or other secondary containment devices per Rule 906.d.(1).	Date: 03/06/2017

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



**Inspected Facilities**Facility ID: 203084 Type: WELL API Number: 001-08491 Status: PR Insp. Status: WK**Workover**Comment: Matco rig in process of well maintenance.Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401203280	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069091</a>
667600138	H2O Tank Netting	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069081">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069081</a>
667600139	Hole in Berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069082</a>
667600141	Separator Fire Tube	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069083">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069083</a>
667600142	Separator Paint	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069084">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069084</a>
667600143	Tank Paint	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069085">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4069085</a>