

**Inspection Photos**  
**Location Name: Mahoney #1**  
**API: 05-123-08110**



**Photo from prior inspection for comparison purposes**



**Photo 1: Stained soil around wellhead, bradenhead not plumbed to surface**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Dier 62N67W 8SESW**  
**API: 05-123-1464**



**Photo from prior inspection for comparison purposes**



**Photo 2: Location looking W, some weeds and detritus at wellhead**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Dier 62N67W 8SESW**  
**API: 05-123-1464**



**Photo from prior inspection for comparison purposes**



**Photo 3: Stained soil in compressor house**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Dier 62N67W 8SESW**  
**API: 05-123-1464**



**Photo from prior inspection for comparison purposes**



**Photo 4: Weeds controlled at separator**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Dier 62N67W 8SESW**  
**API: 05-123-1464**



**Photo from prior inspection for comparison purposes**



**Photo 5: Stained soil in separator house**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Dier 62N67W 8SESW**  
**API: 05-123-1464**



**Photo from prior inspection for comparison purposes**



**Photo 6: Weeds at meter, facing W**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources