

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2017

Submitted Date:

02/14/2017

Document Number:

674103935**FIELD INSPECTION FORM**
 Loc ID 332882 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
, General		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443821	WELL	DG	05/21/2016	LO	123-42389	LAND 14N-32HZ	WK

General Comment:

Inspected Facilities

Facility ID: 443821 Type: WELL API Number: 123-42389 Status: DG Insp. Status: WK

Complaint

Comment: Complaint #:200441031

Field Inspector Assigned: Jeff Rickard

Location #: 332882

Inspection Document #: 674103935

Nature of complaint: Noise

If Sound GPS Coordinates of Survey Location: 40.09113,-104.79230

Inspection Observations:

OGCC inspector returned to location today and wind conditions were suitable to run a sound survey. A sound survey was run from approx 8:30 to 9:30am. HWY 85 was in the direction that the microphone was pointed and inspector observed that hwy noise was the predominant sound in at the time. During the sound survey the location was pumping. Another frac was going on to the east of location, and at another location to the east, a drill out was occurring. The sound survey resulted in a LeqC of 60.5db.
18ADoc#200441093

Corrective Action:

Date:

Well Stimulation

Stimulation Company: _____

Stimulation Type: HYDRAULIC FRAC

Observation:

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>Complaint #:200441031</p> <p>Field Inspector Assigned: Jeff Rickard</p> <p>Location #: 332882</p> <p>Inspection Document #: 674103935</p> <p>Nature of complaint: Noise</p> <p>If Sound GPS Coordinates of Survey Location: 40.09113,-104.79230</p> <p>Inspection Observations:</p> <p>OGCC inspector returned to location today and wind conditions were suitable to run a sound survey. A sound survey was run from approx 8:30 to 9:30am. HWY 85 was in the direction that the microphone was pointed and inspector observed that hwy noise was the predominant sound in at the time. During the sound survey the location was pumping. Another frac was going on to the east of location, and at another location to the east, a drill out was occurring. The sound survey resulted in a LeqC of 60.5db.</p> <p>18ADoc#200441093</p>	rickardj	02/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103936	Photo of sound survey location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075507
674103937	Sound survey.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075508