

Reclamation Inspection

02/13/2017

Operator: Niobrara Illuminating Gas Associates LLC
#63380

Location ID: 403658

Inspection Doc. Number: 682501658

Washington County, CO

NESW Section 17 T2S R49W

Aaron Trujillo
Reclamation Specialist
COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Niobrara Illuminating #63380
Location ID: 403658



Photo 1: Photo taken from the location, facing north. Photo shows vegetation at the well location.



Photo 2: Photo taken from the location, facing east. Photo shows vegetation at the well location.

Inspection Photos
Operator: Niobrara Illuminating #63380
Location ID: 403658



Photo 3: Photo taken from the location, facing south. Photo shows vegetation at the well location.



Photo 4: Photo taken from the location, facing west. Photo shows vegetation at the well location.

Inspection Photos
Operator: Niobrara Illuminating #63380
Location ID: 403658



Photo 5: Photo taken from the north end of the location, facing east. Photo shows area of location remains predominantly bare and exposed soil, with very little desirable perennial vegetative cover. Location has not been stabilized, erosion evident.



Photo 6: Photo taken from the west facing slope on the east end of the location, facing east. Photo shows areas of location that has not been stabilized, erosion evident. Photo also shows areas of location remain predominantly bare and exposed soil

Inspection Photos
Operator: Niobrara Illuminating #63380
Location ID: 403658



Photo 7: Photo taken from the east end of the location, facing south. Photo shows portions of the access road on location have not been reclaimed per reclamation rules. Erosion evident. Dark, stained soil exists and will need to be remediated.



Photo 8: Photo taken from the east end of the location, facing north. Photo shows portions of the access road on location have not been reclaimed per reclamation rules. Erosion evident. Dark, stained soil exists and will need to be remediated. 6' measuring stick for reference.

Inspection Photos
Operator: Niobrara Illuminating #63380
Location ID: 403658



Photo 9: Photo taken from the east end of the location (refer to figures 7 and 8). Photo shows large portions of discolored and rigid soil. These soils need to be remediated or removed. 6' measuring stick for reference.

Inspection Photos
Operator: Niobrara Illuminating #63380
Location ID: 403658



Photo 10: Photo taken from the southeast end of the location, facing north. Photo shows pipe riser, fence and debris remaining on location. Inspection Doc. # 673709790 identified this as a “Gasline tie/well”. Equipment and debris need to be removed.



Photo 11: Photo taken from the southeast end of the location, facing north. Photo shows gravel and debris remaining on location at the “Gasline tie/well”. Equipment and debris need to be removed.