

Inspection Photos  
Location Name: Josey 12-8 (1)  
API: 05-123-10206



Photo from prior inspection for comparison purposes



Photo 1: Signage is for prior operator



**Inspection Photos**  
**Location Name: Josey 12-8 (1)**  
**API: 05-123-10206**



**Photo from prior inspection for comparison purposes**



**Photo 2: Soil at wellhead has been treated**





**Inspection Photos**  
**Location Name: Josey 12-8 (1)**  
**API: 05-123-10206**



**Photo from prior inspection for comparison purposes**



**Photo 3: Stained soil at loadout**



**Inspection Photos**  
**Location Name: Josey 12-8 (1)**  
**API: 05-123-10206**



**Photo from prior inspection for comparison purposes**



**Photo 4: No contents on production tank**



**Inspection Photos**  
**Location Name: Josey 12-8 (1)**  
**API: 05-123-10206**



**Photo 5: Sign is for Noble**

