



photo 1: Pipe risers remain at the location.



photo 2: Facing east at the location. The vegetation is not established in this area.



photo 3: The soils appeared to be compacted in the area where vegetation is not established.



photo 4: East side of the location facing west.



photo 5: The former access road is not recontoured however, vegetation appears to have reestablished.



photo 6: Facing east toward the surrounding undisturbed vegetation.