

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2017

Submitted Date:

02/13/2017

Document Number:

674103934**FIELD INSPECTION FORM**

Loc ID 332882 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
, General		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443821	WELL	DG	05/21/2016	LO	123-42389	LAND 14N-32HZ	WK

General Comment:

Inspected FacilitiesFacility ID: 443821 Type: WELL API Number: 123-42389 Status: DG Insp. Status: WK**Complaint**Comment: Complaint #:200441031Field Inspector Assigned: Jeff RickardLocation #: 332882Inspection Document #: 674103934Nature of complaint: NoiseIf Sound GPS Coordinates of Survey Location: NAInspection Observations:OGCC inspector was on location on 2/13/17, winds were still too high to run a sound survey being 13 mph out of the north. OGCC inspector will return to location on 2/14/17 to try and run a sound survey if wind conditions allow.

Corrective Action:

Date:

Well StimulationStimulation Company: Cal FracStimulation Type: HYDRAULIC FRAC**Observation:**

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____

Date: _____

BradenHeadComment: Braden head is exposed at surface.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Complaint #:200441031 Field Inspector Assigned: Jeff Rickard Location #: 332882 Inspection Document #: 674103934 Nature of complaint: Noise If Sound GPS Coordinates of Survey Location: NA Inspection Observations: OGCC inspector was on location on 2/13/17, winds were still too high to run a sound survey being 13 mph out of the north. OGCC inspector will return to location on 2/14/17 to try and run a sound survey if wind conditions allow.	rickardj	02/13/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401209260	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4074544