

Inspected Facilities

Facility ID: 440898 Type: WELL API Number: 123-41168 Status: DG Insp. Status: WK

Complaint

Comment: [Complaint #:200441037](#)
 Field Inspector Assigned: Jeff Rickard
 Location #: 440920
 Inspection Document #: 674103938
 Nature of complaint: Noise
 If Sound GPS Coordinates of Survey Location: 40.01476,-104.91651
 Inspection Observations:
 OGCC inspector returned to location today and wind conditions were suitable to run a sound survey. The OGCC inspector was able to run a 30 minute survey before the wind speed rose above 30mph. The survey was run on CR4 by the complainants driveway at the GPS coordinates shown above. The survey resulted in a LeqC of 59.6 db
 18ADoc#200441095

Corrective Action: _____ Date: _____

Completion

Operation:
 Date Flowback:
 Contractor:
 Comment: [Awaiting flowback](#)

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Complaint #:200441037 Field Inspector Assigned: Jeff Rickard Location #: 440920 Inspection Document #: 674103938 Nature of complaint: Noise If Sound GPS Coordinates of Survey Location: 40.01476,-104.91651 Inspection Observations: OGCC inspector returned to location today and wind conditions were suitable to run a sound survey. The OGCC inspector was able to run a 30 minute survey before the wind speed rose above 30mph. The survey was run on CR4 by the complainants driveway at the GPS coordinates shown above. The survey resulted in a LeqC of 59.6 db 18ADoc#200441095	rickardj	02/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401210514	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075596
674103939	Photo of sound survey location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075509
674103940	Sound survey.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075510