

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2017

Submitted Date:

02/14/2017

Document Number:

674103942**FIELD INSPECTION FORM**

Loc ID 336263 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
, General		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257305	WELL	PR	06/06/2011	OW	123-19963	HSR GRANT BROTHERS 10-31	PR

General Comment:

Inspected FacilitiesFacility ID: 257305 Type: WELL API Number: 123-19963 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

ComplaintComment: Complaint #:200441080Field Inspector Assigned: Jeff RickardLocation #: 336263Inspection Document #: 674103942Nature of complaint: NoiseIf Sound GPS Coordinates of Survey Location: NAInspection Observations:

OGCC inspector was on location on 2/14/17 in response to a complaint about noise from location. The noise was determined to be coming from the heater fire tube on the separator. Anadarko staff worked on the separator while OGCC inspector was on location. The wind speed was too high to run a noise survey. Anadarko staff was able "tune" the heater to make it quieter while OGCC inspector was on location. Anadarko staff requested complainant's information so their Stakeholder relations could reach out to the resident to continue to work with them to further alleviate the noise issue. Since Anadarko staff was able to "tune" the heater to reduce noise, OGCC inspector considers the complaint closed.

18ADoc#200441097

Corrective Action:

Date:

BradenHeadComment: Braden head is exposed at surface.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>Complaint #:200441080</p> <p>Field Inspector Assigned: Jeff Rickard</p> <p>Location #: 336263</p> <p>Inspection Document #: 674103942</p> <p>Nature of complaint: Noise</p> <p>If Sound GPS Coordinates of Survey Location: NA</p> <p>Inspection Observations:</p> <p>OGCC inspector was on location on 2/14/17 in response to a complaint about noise from location. The noise was determined to be coming from the heater fire tube on the separator. Anadarko staff worked on the separator while OGCC inspector was on location. The wind speed was too high to run a noise survey. Anadarko staff was able "tune" the heater to make it quieter while OGCC inspector was on location. Anadarko staff requested complainant's information so their Stakeholder relations could reach out to the resident to continue to work with them to further alleviate the noise issue. Since Anadarko staff was able to "tune" the heater to reduce noise, OGCC inspector considers the complaint closed. 18ADoc#200441097</p>	rickardj	02/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401210515	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075597