



photo 1: Facing west at the beginning of the access road. The gate and cattle guard remains.



photo 2: A cattle guard and cement structures remain near the beginning of the access road.



photo 3: Facing west. The access road has not been reclaimed and gravel remains.



photo 4: Facing northwest toward the location. The location is fenced and soils have been ripped and partially contoured.



photo 5: Facing northwest toward the location. Portions of the location have been ripped.



photo 6: Facing west along the south side of the location.



photo 7: Facing back toward the east along the south side of the location.



photo 8: Facing north along the west side of the location.



photo 9: Center of the location facing northwest.



photo 10: There are areas at the center of the location where soils appear to be compacted.



photo 11: Northeast corner facing southwest.



photo 12: Facing south toward the surrounding undisturbed vegetation.