

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2017

Submitted Date:

02/15/2017

Document Number:

672500394**FIELD INSPECTION FORM**
 Loc ID 422511 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422494	WELL	PR	09/12/2011	OW	123-33282	JOHNSON PC EE 33-23D	PR
422496	WELL	PR	09/12/2011	OW	123-33283	JOHNSON PC EE 33-10D	PR
422499	WELL	PR	09/12/2011	OW	123-33284	JOHNSON PC EE 33-16D	PR
422502	WELL	PR	09/12/2011	OW	123-33286	JOHNSON PC EE 33-15D	PR
422508	WELL	PR	09/12/2011	OW	123-33289	JOHNSON PC EE 33-09D	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	WIRE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	WIRE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	#		
Comment:	METHANOL PUMP W/CONTAINMENT		
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	<100 BBLS	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Insufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 422494	Type: WELL	API Number: 123-33282	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 422496	Type: WELL	API Number: 123-33283	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 422499	Type: WELL	API Number: 123-33284	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 422502	Type: WELL	API Number: 123-33286	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 422508	Type: WELL	API Number: 123-33289	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		

BradenHead	
Comment:	<div>PLUMBED TO SURFACE</div>
Corrective Action:	<div></div>
Date: <div></div>	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401212522	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077407