



photo 1: The former access road is adequately established with vegetation.



photo 2: South side of the location facing north.



photo 3: West side of the location facing east.



photo 4: It appears that areas with less vegetation cover were recently drill seeded.



photo 5: North side of the location facing south toward the location.



photo 6: East side of the location facing west toward the location.