

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Basic Rig 1652		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 251393 Type: WELL API Number: 123-19196 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7000 Cement Volume (sx): 40 Sacks

Good Return During Job: _____ Cement Type: G

Comment: At time of inspection, crew had completed running scraper to bottom of hole and were waiting on hydro test contractor. Cement scheduled for PM, plans call for cast iron bridge plug at 7,000 feet.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Routine PA inspection. Company representative on location: Edgar.	carlilec	02/17/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401213611	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4078499