

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2017

Submitted Date:

02/26/2017

Document Number:

680101536**FIELD INSPECTION FORM**

Loc ID 446582	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	Status Summary:
		2A Doc Num: _____	<input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information:			Findings:
OGCC Operator Number: <u>10447</u>			
Name of Operator: <u>URSA OPERATING COMPANY LLC</u>			
Address: <u>1050 17TH STREET #1700</u>			
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80265</u>	11 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
		jlind@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446573	WELL	XX	07/14/2016		045-23262	BMC D 32C-18-07-95	CI
446574	WELL	XX	07/14/2016		045-23263	BMC D 44D-07-07-95	CI
446575	WELL	XX	07/14/2016		045-23264	BMC D 41C-18-07-95	CI
446576	WELL	XX	07/14/2016		045-23265	BMC D 41A-18-07-95	CI
446577	WELL	XX	07/14/2016		045-23266	BMC D 34B-07-07-95	CI
446578	WELL	XX	07/14/2016		045-23267	BMC D 31A-18-07-95	CI
446579	WELL	XX	07/14/2016		045-23268	BMC D 34C-07-07-95	CI
446580	WELL	XX	07/14/2016		045-23269	BMC D 32A-18-07-95	CI
446581	WELL	XX	07/14/2016		045-23270	BMC D 32B-18-07-95	CI
446583	WELL	XX	07/14/2016		045-23271	BMC D 31B-18-07-95	CI
446584	WELL	XX	07/14/2016		045-23272	BMC D 32D-18-07-95	CI
446585	WELL	XX	07/14/2016		045-23273	BMC D 34D-07-07-95	CI
446586	WELL	XX	07/14/2016		045-23274	BMC D 32E-18-07-95	CI
446587	WELL	XX	07/14/2016		045-23275	BMC D 34A-07-07-95	CI
446588	WELL	XX	07/14/2016		045-23276	BMC D 31C-18-07-95	CI
446589	WELL	XX	07/14/2016		045-23277	BMC D 31D-18-07-95	CI
446765	WELL	XX	07/20/2016		045-23278	BMC D 41B-18-07-95	CI
447694	WELL	XX	09/09/2016		045-23307	BMC D 11C-18-07-95	CI
447696	WELL	XX	09/09/2016		045-23308	BMC D 12C-18-07-95	CI
447697	WELL	XX	09/09/2016		045-23309	BMC D 11D-18-07-95	CI
447699	WELL	XX	09/09/2016		045-23311	BMC D 12B-18-07-95	CI
447700	WELL	XX	09/09/2016		045-23312	BMC D 12A-18-07-95	CI
447701	WELL	XX	09/10/2016		045-23313	BMC D 21C-18-07-95	CI

447702	WELL	XX	09/10/2016		045-23314	BMC D 22B-18-07-95	CI
447703	WELL	XX	09/10/2016		045-23315	BMC D 22A-18-07-95	CI
447704	WELL	XX	09/10/2016		045-23316	BMC D 21B-18-07-95	CI
447705	WELL	XX	09/10/2016		045-23317	BMC D 21D-18-07-95	CI
447714	WELL	XX	09/10/2016		045-23326	BMC D 22C-18-07-95	CI

General Comment:

This is a Construction and Stormwater inspection. Form 42 (Notice of Construction) has been Filed for this Location; Start Date 2/21/2017. Conditions at time of Inspection were 50 degrees with Low Clouds; no precipitation, though remnants of SW Flow was evident. Location has Access Road, various Bmps, basic grubbing Operations already installed & performed by Pipeline Co using Location as Construction and Staging Area.

Location Construction

Location ID: 446582 CDP: _____

Comment: This was the First day of Location Construction by Operator; Pipeline Construction is going on Simultaneously at Western edge of Location and to NE off of Access Road.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	No		

Comments: Erosion BMPs: Slope Roughening scheduled for Access Road slopes into ditches, as Rill erosion & sediment migration is evident.

Other BMPs: _____

Corrective Action: _____ Date: _____

WADDLES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Wattles in Access Road Ditches are scheduled for repair as presently there is evidence of undercutting & overflow of Sediment.

Other BMPs: _____

Corrective Action: _____ Date: _____

WADDLES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Wattles are installed at SW Perimeter of Location.

Other BMPs: _____

Corrective Action: _____ Date: _____

RETENTION PONDS	Yes		
-----------------	-----	--	--

Comments: Erosion BMPs: Retention Pond/Sediment Trap at Access Road Culvert Discharge point is scheduled for cleanout & enlargement.

Other BMPs: _____

Corrective Action: _____ Date: _____

DITCHES	Yes		
Comments: Erosion BMPs: Ditches on Access Road are scheduled for stablization with Gravel.			
Other BMPs:			
Corrective Action: _____			Date: _____
SLOPE ROUGHENING	No		
Comments: Erosion BMPs: Roughening is scheduled for NE perimeter of Location.			
Other BMPs:			
Corrective Action: _____			Date: _____

Comment: **I**Operator was assessing SW BMPs Previously installed by Pipeline company at time of Inspection. Pipeline Construction is ongoing at Western edge of Location. SW BMP repairs & installation was occurring by second site visit the Day of this Inspection. Refer to Photos attached for more detail

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>446573</u>	Type: <u>WELL</u>	API Number: <u>045-23262</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446574</u>	Type: <u>WELL</u>	API Number: <u>045-23263</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446575</u>	Type: <u>WELL</u>	API Number: <u>045-23264</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446576</u>	Type: <u>WELL</u>	API Number: <u>045-23265</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446577</u>	Type: <u>WELL</u>	API Number: <u>045-23266</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446578</u>	Type: <u>WELL</u>	API Number: <u>045-23267</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446579</u>	Type: <u>WELL</u>	API Number: <u>045-23268</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446580</u>	Type: <u>WELL</u>	API Number: <u>045-23269</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446581</u>	Type: <u>WELL</u>	API Number: <u>045-23270</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446583</u>	Type: <u>WELL</u>	API Number: <u>045-23271</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446584</u>	Type: <u>WELL</u>	API Number: <u>045-23272</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446585</u>	Type: <u>WELL</u>	API Number: <u>045-23273</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446586</u>	Type: <u>WELL</u>	API Number: <u>045-23274</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446587</u>	Type: <u>WELL</u>	API Number: <u>045-23275</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446588</u>	Type: <u>WELL</u>	API Number: <u>045-23276</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446589</u>	Type: <u>WELL</u>	API Number: <u>045-23277</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446765</u>	Type: <u>WELL</u>	API Number: <u>045-23278</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447694</u>	Type: <u>WELL</u>	API Number: <u>045-23307</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447696</u>	Type: <u>WELL</u>	API Number: <u>045-23308</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Inspector Name: Colby, Lou

Facility ID: 447697	Type: WELL	API Number: 045-23309	Status: XX	Insp. Status: CI
Facility ID: 447699	Type: WELL	API Number: 045-23311	Status: XX	Insp. Status: CI
Facility ID: 447700	Type: WELL	API Number: 045-23312	Status: XX	Insp. Status: CI
Facility ID: 447701	Type: WELL	API Number: 045-23313	Status: XX	Insp. Status: CI
Facility ID: 447702	Type: WELL	API Number: 045-23314	Status: XX	Insp. Status: CI
Facility ID: 447703	Type: WELL	API Number: 045-23315	Status: XX	Insp. Status: CI
Facility ID: 447704	Type: WELL	API Number: 045-23316	Status: XX	Insp. Status: CI
Facility ID: 447705	Type: WELL	API Number: 045-23317	Status: XX	Insp. Status: CI
Facility ID: 447714	Type: WELL	API Number: 045-23326	Status: XX	Insp. Status: CI

COGCC Comments

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to Photos attached for more detail	colbyl	02/26/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101537	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4084175