

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2017

Submitted Date:

02/26/2017

Document Number:

680101538**FIELD INSPECTION FORM**

Loc ID 446582	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	-------------------------------	---	-------------------

**Operator Information:**

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 1050 17TH STREET #1700

City: DENVER State: CO Zip: 80265

**Status Summary:**

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		jlind@ursaresources.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446573	WELL	XX	07/14/2016		045-23262	BMC D 32C-18-07-95	CI
446574	WELL	XX	07/14/2016		045-23263	BMC D 44D-07-07-95	CI
446575	WELL	XX	07/14/2016		045-23264	BMC D 41C-18-07-95	CI
446576	WELL	XX	07/14/2016		045-23265	BMC D 41A-18-07-95	CI
446577	WELL	XX	07/14/2016		045-23266	BMC D 34B-07-07-95	CI
446578	WELL	XX	07/14/2016		045-23267	BMC D 31A-18-07-95	CI
446579	WELL	XX	07/14/2016		045-23268	BMC D 34C-07-07-95	CI
446580	WELL	XX	07/14/2016		045-23269	BMC D 32A-18-07-95	CI
446581	WELL	XX	07/14/2016		045-23270	BMC D 32B-18-07-95	CI
446583	WELL	XX	07/14/2016		045-23271	BMC D 31B-18-07-95	CI
446584	WELL	XX	07/14/2016		045-23272	BMC D 32D-18-07-95	CI
446585	WELL	XX	07/14/2016		045-23273	BMC D 34D-07-07-95	CI
446586	WELL	XX	07/14/2016		045-23274	BMC D 32E-18-07-95	CI
446587	WELL	XX	07/14/2016		045-23275	BMC D 34A-07-07-95	CI
446588	WELL	XX	07/14/2016		045-23276	BMC D 31C-18-07-95	CI
446589	WELL	XX	07/14/2016		045-23277	BMC D 31D-18-07-95	CI
446765	WELL	XX	07/20/2016		045-23278	BMC D 41B-18-07-95	CI
447694	WELL	XX	09/09/2016		045-23307	BMC D 11C-18-07-95	CI
447696	WELL	XX	09/09/2016		045-23308	BMC D 12C-18-07-95	CI
447697	WELL	XX	09/09/2016		045-23309	BMC D 11D-18-07-95	CI
447699	WELL	XX	09/09/2016		045-23311	BMC D 12B-18-07-95	CI
447700	WELL	XX	09/09/2016		045-23312	BMC D 12A-18-07-95	CI
447701	WELL	XX	09/10/2016		045-23313	BMC D 21C-18-07-95	CI

447702	WELL	XX	09/10/2016		045-23314	BMC D 22B-18-07-95	CI
447703	WELL	XX	09/10/2016		045-23315	BMC D 22A-18-07-95	CI
447704	WELL	XX	09/10/2016		045-23316	BMC D 21B-18-07-95	CI
447705	WELL	XX	09/10/2016		045-23317	BMC D 21D-18-07-95	CI
447714	WELL	XX	09/10/2016		045-23326	BMC D 22C-18-07-95	CI

**General Comment:**

This is a Construction and Stormwater Inspection. Form 42 (Notice of Construction) has been Filed for this Location; Start Date 2/21/2017. Conditions at time of Inspection were 50 degrees, Scattered Clouds, with intermittent Gusty Winds.

**Location Construction**

Location ID: 446582 CDP: \_\_\_\_\_

Comment: Top Soil has been Salvaged and will be used for large Perimeter Berms now being built that will be the Interim Reclamation for Location as Pad will not be Pulled back in after completion.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: Re: Dust Control: Water Truck was not on site as specified in Dust Control BMP.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
RETENTION PONDS	Yes		

Comments: Erosion BMPs: Sediment trap has been cleaned enlarged

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

WADDLES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Wattles have been reset.

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Access Road Ditches have been stabilized

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

SLOPE ROUGHENING	Yes		
------------------	-----	--	--

Comments: Erosion BMPs: Slope roughening has been Implemented along Access Road

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

SLOPE ROUGHENING	Yes		
Comments: Erosion BMPs: <span style="color: red;">Roughening has been implemented along NE edge of Location.</span>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action: _____			Date: _____

  

WADDLES	Yes		
Comments: Erosion BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Other BMPs: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>			
Corrective Action: _____			Date: _____

  

**Comment:** Re: Dust Control: Construction activities shut down for period time due to Gusty Winds blowing fugitive Dust. Water Truck was not on site. Water was brought in for Dust abatement and Construction continued.

**Corrective Action:****Date:** \_\_\_\_\_

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

Inspected Facilities				
Facility ID: <u>446573</u>	Type: <u>WELL</u>	API Number: <u>045-23262</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446574</u>	Type: <u>WELL</u>	API Number: <u>045-23263</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446575</u>	Type: <u>WELL</u>	API Number: <u>045-23264</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446576</u>	Type: <u>WELL</u>	API Number: <u>045-23265</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446577</u>	Type: <u>WELL</u>	API Number: <u>045-23266</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446578</u>	Type: <u>WELL</u>	API Number: <u>045-23267</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446579</u>	Type: <u>WELL</u>	API Number: <u>045-23268</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446580</u>	Type: <u>WELL</u>	API Number: <u>045-23269</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446581</u>	Type: <u>WELL</u>	API Number: <u>045-23270</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446583</u>	Type: <u>WELL</u>	API Number: <u>045-23271</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446584</u>	Type: <u>WELL</u>	API Number: <u>045-23272</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446585</u>	Type: <u>WELL</u>	API Number: <u>045-23273</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446586</u>	Type: <u>WELL</u>	API Number: <u>045-23274</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446587</u>	Type: <u>WELL</u>	API Number: <u>045-23275</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446588</u>	Type: <u>WELL</u>	API Number: <u>045-23276</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446589</u>	Type: <u>WELL</u>	API Number: <u>045-23277</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446765</u>	Type: <u>WELL</u>	API Number: <u>045-23278</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447694</u>	Type: <u>WELL</u>	API Number: <u>045-23307</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447696</u>	Type: <u>WELL</u>	API Number: <u>045-23308</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Inspector Name: Colby, Lou

Facility ID: 447697	Type: WELL	API Number: 045-23309	Status: XX	Insp. Status: CI
Facility ID: 447699	Type: WELL	API Number: 045-23311	Status: XX	Insp. Status: CI
Facility ID: 447700	Type: WELL	API Number: 045-23312	Status: XX	Insp. Status: CI
Facility ID: 447701	Type: WELL	API Number: 045-23313	Status: XX	Insp. Status: CI
Facility ID: 447702	Type: WELL	API Number: 045-23314	Status: XX	Insp. Status: CI
Facility ID: 447703	Type: WELL	API Number: 045-23315	Status: XX	Insp. Status: CI
Facility ID: 447704	Type: WELL	API Number: 045-23316	Status: XX	Insp. Status: CI
Facility ID: 447705	Type: WELL	API Number: 045-23317	Status: XX	Insp. Status: CI
Facility ID: 447714	Type: WELL	API Number: 045-23326	Status: XX	Insp. Status: CI

#### COGCC Comments

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to attached inspection photos.	colbyl	02/26/2017

#### Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101539	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4084176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4084176</a>