

Photo#1:


View of Location From 330 E Rd to SE. Red dotted lines indicate Top soil salvaged & stored around Location Perimeter. BMPs have not been installed along outside base of Soil piles to prevent Run-off / Sediment Migration to nearby surface water or any drainages leading to surface water. North Perimeter is of most Concern



March 3,2017

Photo#2:

View from Location Edge to NW.



March 3,2017

Photo#3:

Culvert , Gravel & Wattles Installed at beginning of Access Rd at point where it diverts off Local, Ground Hog Gulch Rd.

Photo#4:



March 3,2017

Photo#5:

Culvert empties into Ditch that runs along base of Access Rd.



March 3,2017

Photo#6:

No BMPs contain Top Soil around perimeter of Location or Access Rd.



Photo#7:
Overview of Work on Location to SW.



March 3, 2017