

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/19/2017

Submitted Date:

03/01/2017

Document Number:

673714816**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
309655 _____ Sherman, Susan _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10399Name of Operator: NIGHTHAWK PRODUCTION LLCAddress: 1805 SHEA CENTER DR #290City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Henkin, Joyce	(303) 407-9609	joycehenkin@nighthawkenergy.com	
Spear, Sam	(970) 554-1988	samspear@nighthawkenergy.com	
Morse, Jennifer	(303) 692-3240	jennifer.morse@state.co.us	CDPHE AQCD
Rezendes, Joe		JoeRezendes@nighthawkenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300214	WELL	PR	06/15/2016	OW	073-06361	Steamboat Hansen 8-10	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	treaters		
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign at CR 35		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Heater Treater	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:	west pilot light not on		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
GLYCOL	1	200 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Sherman, Susan

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	YES		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	300214	Type:	WELL	API Number:	073-06361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Dec 2016 reported to COGCC database.								
Corrective Action:				Date:					

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☒ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: Clear Temperature: 44 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:05	AM	11:22	AM

Equipment
Other
Oil Tank(s)
Separation Equipment
Water Tank(s)

Comment: 3 ECDs venting, 3 treaters venting, glycol tank ventingCorrective
Action:

Date:

COGCC Comments

Comment	User	Date
<u>Flir Survey only</u>	ShermaSe	03/03/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673714960	Nighthawk Steamboat Hansen 8-10 Equipment Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090569
673714961	Nighthawk Steamboat Flir Survey of ECD and treaters	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090570
673714962	Nighthawk Steamboat Flir Survey of glycol tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090571