

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2017

Submitted Date:

03/02/2017

Document Number:

680401172**FIELD INSPECTION FORM**
 Loc ID 335180 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Rants, John	970-319-0013	jrant@vnrlc.com	Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260918	WELL	PR	12/16/2002	GW	045-07922	PORTER FEDERAL 12-28	PR
279622	WELL	PR	12/29/2005	GW	045-11061	SPECIALTY FEDERAL 14D-28-692	PR
279623	WELL	PR	12/09/2005	GW	045-11062	SPECIALTY FEDERAL 13C-28-692	PR
290234	WELL	IJ	04/17/2007	DSPW	045-14054	SPECIALTY 13A-28-692 SWD	AC

General Comment:

Routine UIC Inspection.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence. UIC well in housing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 260918 Type: WELL API Number: 045-07922 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: _____

Date: _____

Facility ID: 279622 Type: WELL API Number: 045-11061 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: _____

Date: _____

Facility ID: 279623 Type: WELL API Number: 045-11062 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: _____

Date: _____

Facility ID: 290234 Type: WELL API Number: 045-14054 Status: IJ Insp. Status: AC**Underground Injection Control**

UIC Violation: _____

Maximum Injection Pressure: _____

UIC RoutineInj./Tube: Pressure or inches of Hg 1957
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: CZ-CRTC: Pressure or inches of Hg 333

Previous Test Pressure _____

Last MIT: 01/12/2015Brhd: Pressure or inches of Hg 0

Previous Test Pressure _____

AnnMTReq: _____

Comment: Routine UIC Inspection. Well shut in. No active injection at time of inspection. Pressures recorded 3/1/2017.

Corrective Action: _____

Date: _____

Method of Injection: PUMP FEED

Test Type: _____

Tbg psi: _____

Csg psi: _____

BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass	Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401224156	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4089362