

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2017

Submitted Date:

03/10/2017

Document Number:

667601535**FIELD INSPECTION FORM**

Loc ID 319874	Inspector Name: Kraich, Adam	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 13 Number of Comments 7 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>27635</u> Name of Operator: <u>ENERGY SEARCH CO ADBA ENERGY SEARCH CO</u> Address: <u>PO BOX 1896</u> City: <u>EDWARDS</u> State: <u>CO</u> Zip: <u>81632</u>				

**Contact Information:**

Contact Name	Phone	Email	Comment
Marisco, Joe	(303) 320-6546	joemarisco@yahoo.com	
Robuck, Don		buckaroo51@msn.com	<a href="#">ALL Inspections</a>
Robuck, Don		DON_Roebuck@MSN.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201682	WELL	SI	09/02/2014	OW	001-07085	KORTUM 3	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate.		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No signage at wellhead or pumping unit at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/10/2017
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency phone number has been disconnected.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 04/10/2017
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Uncontrolled weeds around treater house and berms. See photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	04/10/2017
Type	OTHER		
Comment:	Stained soil around oil tanks in berm, see photo.		
Corrective Action:	Remove and remEDIATE stained soil.	Date:	04/10/2017
Type	TRASH		
Comment:	Trash at wellhead, see photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	04/10/2017
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Vertical Heated Separator	# 1		corrective date
Comment:	Separator with shed. Burner/Fire tube access has no cover allowing access to wildlife.		
Corrective Action:	Replace burner cover, or install wildlife protection measures.		Date: 04/10/2017

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor on pumping unit.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:	Tanks are in disrepair, north tank has no valve at load line and is leaking fluid into load line bucket causing it to breach. See photo.					
Corrective Action:						Date:

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 201682 Type: WELL API Number: 001-07085 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Well has been SI since September 2011, No production reported since February 2015.Corrective Action: No current MIT on record or delinquent as required by Rule 326 -Contact COGCC\_Engineering@state.co.us with resolution plan.Date: 03/20/2017**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667601536	Battery ID	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095920">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095920</a>
667601537	Breaching load line bucket	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095921</a>
667601538	Weeds at separator and berms	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095922</a>
667601539	Pumping unit, no signage, trash	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095923">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095923</a>
667601540	Pumping unit, no signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095924</a>