

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/22/2017

Document Number:

674901481**FIELD INSPECTION FORM**

Loc ID 325165 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214181	WELL	PR	10/01/2013	GW	067-05501	MILLER MESAVERDE UNIT 1	EI

**General Comment:**

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Miller MV #1. For the most recent field inspection report of this facility, please refer to document #674600708.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	UNUSED EQUIPMENT	
Comment:	Steel beam laying along east side of location.	
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date: 03/22/2017

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 2		
Comment:	Only northern two rig anchor markers were observed.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		37.128447,-107.755605
Comment:	Expanded metal cover. Tank is rusted along bottom and sides.				
Corrective Action:				Date:	

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	20 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Miller MV #1. For the most recent field inspection report of this facility, please refer to document #674600708.	hughesj	02/22/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401216791	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081734">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081734</a>
674901482	Western side of location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081721">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081721</a>
674901483	20 bbl. PW open topped tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081722">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081722</a>
674901484	Steel beam along eastern edge of location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081723">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081723</a>