

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/23/2017

Document Number:

674901491**FIELD INSPECTION FORM**

Loc ID 325143 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	
Lindeman, Terry	(505) 632-3476 Ext 210	tlindeman@elmridge.net	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214117	WELL	PR	10/31/1959	GW	067-05427	JULIAN MVRD UNIT 1	EI

**General Comment:**

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Julian MV #1. For the most recent field inspection report of this facility, please refer to document #667700294.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Drop out tank for domestic tap.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	SE marker not found.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.106348,-107.763166
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	10 bbl.
Other (Type)	

**Berms**

Inspector Name: Hughes, Jim

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214117	Type:	WELL	API Number:	067-05427	Status:	PR	Insp. Status:	EI

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass			

Comment: [Storm water erosional channel present along side of secondary containment berm.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 03/23/2017

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Julian MV #1. For the most recent field inspection report of this facility, please refer to document #667700294. Storm water erosional channel on location is incising into secondary containment berm.	hughesj	02/23/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401217573	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082569</a>
674901492	10 bbl. PW AST	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082566</a>
674901493	Storm water eroding secondary containment berm.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082567">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082567</a>
674901494	Drop out tank and domestic gas tap.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082568</a>