



**Inspected Facilities**

Facility ID: 442304 Type: WELL API Number: 123-41789 Status: DG Insp. Status: WK

**Complaint**

Comment: Complaint DOC#2000441146.  
OGCC inspector returned to location on 3/6/17 but wind speeds were to high to run a sound survey or investigate odors. Red flag warnings are in the area and are effective through 3/7/17. OGCC inspector will return to location on 3/7/17 if wind speeds calm down and a sound survey is able to be run.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Well Stimulation**

Stimulation Company: Liberty Stimulation Type: \_\_\_\_\_  
 Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
 Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
 Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
 Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401226490	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4091532">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4091532</a>