

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2017

Submitted Date:

03/10/2017

Document Number:

667601535**FIELD INSPECTION FORM**
 Loc ID 319874 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH COAddress: PO BOX 1896City: EDWARDS State: CO Zip: 81632**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Robuck, Don		buckaroo51@msn.com	ALL Inspections
Robuck, Don		DON_Roebuck@MSN.COM	
Marisco, Joe	(303) 320-6546	joemarisco@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201682	WELL	SI	09/02/2014	OW	001-07085	KORTUM 3	SI

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Adequate.		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	No signage at wellhead or pumping unit at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 04/10/2017
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency phone number has been disconnected.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 04/10/2017
Good Housekeeping:			
Type	WEEDS		
Comment:	Uncontrolled weeds around treater house and berms. See photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 04/10/2017
Type	TRASH		
Comment:	Trash at wellhead, see photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 04/10/2017
Type	OTHER		
Comment:	Stained soil around oil tanks in berm, see photo.		
Corrective Action:	Remove and remEDIATE stained soil.		Date: 04/10/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Vertical Heated Separator	# 1		corrective date
Comment:	Separator with shed. Burner/Fire tube access has no cover allowing access to wildlife.		
Corrective Action:	Replace burner cover, or install wildlife protection measures.		Date: 04/10/2017

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor on pumping unit.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:	Tanks are in disrepair, north tank has no valve at load line and is leaking fluid into load line bucket causing it to breach. See photo.					
Corrective Action:						Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 201682 Type: WELL API Number: 001-07085 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Well has been SI since September 2011, No production reported since February 2015.Corrective Action: No current MIT on record or delinquent as required by Rule 326 -Contact COGCC_Engineering@state.co.us with resolution plan.Date: 03/20/2017**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401230869	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095933
667601536	Battery ID	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095920
667601537	Breaching load line bucket	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095921
667601538	Weeds at separator and berms	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095922
667601539	Pumping unit, no signage, trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095923
667601540	Pumping unit, no signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095924