

Location

Lease Road:			
Type	Access		
comment:	Adequate.		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Emergency contact phone number has been disconnected.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 04/10/2017

Good Housekeeping:			
Type	WEEDS		
Comment:	Uncontrolled weeds at wellhead.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 04/10/2017

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 200787 Type: WELL API Number: 001-06190 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Well has been SI since Sep. 2011, No production reported since Feb. 2015. No MIT on File.Corrective Action: No current MIT on record or delinquent as required by Rule 326 - Contact COGCC_Engineering@state.co.us with resolution plan.Date: 03/20/2017**COGCC Comments**

Comment	User	Date
<u>Well shares battery with Kortum 3 (API 001-07085), all battery equipment and issues are listed on its inspection form (DOC# 667601535).</u>	kraicha	03/10/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401230870	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095934
667601542	Weeds at pumping unit.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095925