

Location			
Lease Road:			
Type	Access		
comment:	Road to wellhead is covered with weeds. See Photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	04/10/2017
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact phone number has been disconnected.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/10/2017
Good Housekeeping:			
Type	WEEDS		
Comment:	Uncontrolled weeds dominate entire location, wellhead, tank battery, and separator. See Photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	04/10/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas fired engine on pumping unit.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		,
Comment:	Open top fiberglass.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shared with oil tank, see corrective action.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berms have overgrowth of weeds. See photos.			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			
				Date: 04/10/2017

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 203295 Type: WELL API Number: 001-08804 Status: PR Insp. Status: PR**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: Well has been SI since Sep. 2014, no production reported since Feb. 2015. No MIT on file.Corrective Action: No current MIT on record or delinquent as required by Rule 326 - Contact COGCC_Engineering@state.co.us with resolution plan.Date: 03/27/2017**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401230871	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095935
667601544	Wellhead access road	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095926
667601545	Weeds at wellhead and pumping unit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095927
667601546	Weeds at wellhead and pumping unit 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095928
667601547	Weeds at wellhead and pumping unit 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095929
667601548	Tank battery ID	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095930
667601549	Weeds at battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095931
667601550	Weeds at separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095932