

Inspected Facilities

Facility ID: 441889 Type: WELL API Number: 123-41551 Status: DG Insp. Status: WK

Complaint

Comment: Complaint #:200441164
 Nature of complaint: Sound, Odor, Lighting
 If Sound GPS Coordinates of Survey Location: 40.09112, -104.79263
 Inspection Observations:
 OGCC inspector was on location on 3/10/17 at 10:00AM. Wind conditions were calm enough to run a sound survey. The location was actively pumping during the sound survey. The sound survey resulted in a Leq C of 61.7 db.
 No odors were detected at the residence at the time of inspection.
 All light towers on location were pointed downward and inward. Residence is farther than 1,000 ft away from location.
 18A:200441195

Corrective Action: _____ Date: _____

Well Stimulation

Stimulation Company: Liberty Stimulation Type: HYDRAULIC FRAC
 Other: _____

Observation:

Maximum Casing Recorded: _____ PSI Tubing: _____
 Surface: _____ Intermediate: _____
 Production: _____ Instantaneous Shut-In Pressure (ISIP) _____
 Bradenhead Psi: _____ Frac Flow Back: _____ Fluid: _____ Gas: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401230415	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095495
674103964	Photo of sound survey location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095492
674103965	Sound Survey	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095493