

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2017

Submitted Date:

03/09/2017

Document Number:

672500461**FIELD INSPECTION FORM**

Loc ID 438989 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438986	WELL	DG	09/21/2016	LO	123-40247	Klein 19N-312	WO
438987	WELL	DG	11/17/2016	LO	123-40248	Klein 19M-402	WO
438990	WELL	DG	10/16/2016	LO	123-40250	Klein 19M-232	WO

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 438986 Type: WELL API Number: 123-40247 Status: DG Insp. Status: WO**Completion**Operation: Drillout

Date Flowback:

Contractor:

Comment: TITAN AND BWS PERFORMING DRILL OUT AND FLOW BACK ON LOCATION

Corrective Action:

Date:

Facility ID: 438987 Type: WELL API Number: 123-40248 Status: DG Insp. Status: WO**Completion**Operation: Drillout

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Facility ID: 438990 Type: WELL API Number: 123-40250 Status: DG Insp. Status: WO**Completion**Operation: DrilloutDate Flowback: 03/08/2017

Contractor:

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**

Survey Type: \_\_\_\_\_

Current Operations: ☐ Production ☐ Workover ☒ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: 40.389610 Long: -104.592580

Wind: Light Speed: 1-5 (mph) Direction From: NWW Weather: Partly Temperature: 67 (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
12:12	PM	12:14	

Equipment
Other
Flowback tank(s)

Comment: DRILL OUT RIG OBSERVED

Corrective

Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401232872	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097811">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097811</a>
672500462	THERMAL IMAGERY DRILL OUT FLOW BACK	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097796">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097796</a>