

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2017

Submitted Date:

03/15/2017

Document Number:

685502244**FIELD INSPECTION FORM**

Loc ID 319864 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 41550Name of Operator: TYLER ROCKIES EXPLORATION LTDAddress: P O BOX 119City: TYLER State: TX Zip: 75710-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments9 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strawn, Mark	903-595-4886	texcomo@sbcglobal.net	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201647	WELL	PR	12/01/2016	OW	001-07050	FLADER INDUSTRIES 1	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	RUTS ON ROAD TO WELLHEAD		
Corrective Action	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S.	Date:	04/05/2017
Type	Main		
comment:	ROADWAY AROUND LOCATION HAS DEEP MRUTS		
Corrective Action	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S.	Date:	04/05/2017

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: OK

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	UNUSED EQUIPMENT TREATER NEEDS REMOVED UNUSED EQUIPMENT		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	
Type	UNUSED EQUIPMENT		
Comment:	SUCKER RODS, BELT GAURD AND USED BELTS		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	04/05/2017
Type	TRASH		
Comment:	TRASH AROUND PUMP JACK		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	04/05/2017

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	Truck Loadout	<= 1 bbl		
Comment: SOILED DIRT AROUND LOAD LINE AND AROUND TANKS				
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	04/05/2017
Lube Oil	Pump Jack	<= 1 bbl		
Comment: SOILED DIRT AROUND MOTOR				
Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	04/05/2017

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment: PIG WIRE AND ANGLE FENCE			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: 1 PROPANE BOTTLE AT PUMP JACK			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: PARAFIN SOLVENT, PUMP, AND CONTAINER			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment: SE CORNER N39.45714 W-104.01720			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	BERMS IN DIS-REPAIR			
Corrective Action:	Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G.			Date: 04/05/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.457120,-104.016990
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	BERMS IN DIS-REPAIR			
Corrective Action:	Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G.			Date: 04/05/2017

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	201647	Type:	WELL	API Number:	001-07050	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									
BradenHead									
Comment: BRADENHEAD PLUMBED TO SURFACE									
Corrective Action: _____ Date: _____									

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401234865	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099758">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099758</a>
685502245	BATTERY NSIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099494">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099494</a>
685502246	SOILED DIRT LOAD LINE VALVE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099495">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099495</a>
685502247	SOILED DIRT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099496</a>
685502248	RUTS IN ROAD WAY AND AT WATER PROD TANK	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099497</a>
685502249	REPAIR BERMS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099498</a>
685502250	BERMS AROUND WATER AND COVERED PIT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099499</a>
685502251	BERMS NEED REPAIRED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099500</a>
685502252	UNUSED EQUIPMENT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099501</a>
685502253	BERMS NEED REPAIRED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099502</a>
685502254	BERMS AT BATTERY	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099503">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099503</a>
685502255	WELL SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099504">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099504</a>
685502256	SUCKER AND POLISH ROD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099505</a>
685502257	SOILED DIRT WELLHEAD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099506</a>
685502258	CLEAN UP OIL STAINED SOIL	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099507">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099507</a>
685502259	5 GALLON BUCKETS TRASH	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099508</a>
685502260	UNUSED EQUIPMENT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099509</a>
685502261	BELT GAURD AND TRASH	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099510">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099510</a>