

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2017

Submitted Date:

03/23/2017

Document Number:

670201427**FIELD INSPECTION FORM**

Loc ID 442832 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lind, Jennifer	(720) 508-8362	jlind@ursaresources.com	<a href="#">All Inspections</a>
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>
Kubeczko, Dave		dave.kubeczko@state.co.us	

**General Comment:**[Engineering group inspection to observe flowback process.](#)

**Location Construction**

Location ID: 442832 CDP: \_\_\_\_\_

**Comment:** Green completions equipment on location operated by LEC. Flowback of two wells occurring during inspection. Hydraulic stimulation of another well being performed by Haliburton. No propanant being used during stimulation. Flowback equipment consists of an inclined unit to separate junk from plug drill out, a vertical separator for each well being flowed back, and a horizontal unit for additional separation. Fluids are then piped to tanks and gas is routed to an enclosed flare until salable. Two enclosed flares on location for flowback and two additional combustors for production equipment. Temporary frac tanks on location to store produced water are connected to a pipeline system.

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

**Name:** \_\_\_\_\_ **Address:** \_\_\_\_\_

**Phone Number:** \_\_\_\_\_ **Cell Phone:** \_\_\_\_\_

Operator Rep. Contact Information:

**Landman Name:** \_\_\_\_\_ **Phone Number:** \_\_\_\_\_

**Date Onsite Request Received:** \_\_\_\_\_ **Date of Rule 306 Consultation:** \_\_\_\_\_

**Request LGD Attendance:** \_\_\_\_\_

LGD Contact Information:

**Name:** \_\_\_\_\_ **Phone Number:** \_\_\_\_\_ **Agreed to Attend:** \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_