

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2017

Submitted Date:

03/24/2017

Document Number:

675204064

FIELD INSPECTION FORM

Loc ID 418985 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|-----------------------------|---|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | NW Supervisor |
| Bankert, Wayne | (970) 683-5419 | wbankert@laramie-energy.com | Senior Regulatory & Environmental Coordinator |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 419015 | WELL | PR | 05/06/2013 | GW | 077-10101 | Bruton 30-16B | PR |
| 419019 | WELL | PR | 07/09/2013 | GW | 077-10102 | Bruton 30-10B | PR |
| 419027 | WELL | PR | 05/06/2013 | OG | 077-10103 | Bruton 30-08B | PR |
| 419043 | WELL | PR | 04/29/2013 | OG | 077-10104 | Bruton 30-06B | PR |

General Comment:

Follow up to inspection Doc#675203849. CA's have not been met from previous inspection. See fence section of inspection form and attached photos.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--|-------|------------|
| Type | WELLHEAD | | |
| Comment: | Wire fence is damaged. Potential wildlife or livestock hazard. See attached photo. | | |
| Corrective Action: | Repair fence. | Date: | 03/17/2017 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|----------------------|----------|-----------|---------|--------|
| CONDENSATE | 3 | 400 BBLs | STEEL AST | | , |
| Comment: | <input type="text"/> | | | | |
| Corrective Action: | <input type="text"/> | | | | Date: |

Paint

| | | |
|------------------|----------------------|--|
| Condition | Adequate | |
| Other (Content) | <input type="text"/> | |
| Other (Capacity) | <input type="text"/> | |
| Other (Type) | <input type="text"/> | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | <input type="text"/> | | | |
| Corrective Action: | <input type="text"/> | | | Date: |

Venting:

| | | | |
|--------|----|--|--|
| Yes/No | NO | | |
|--------|----|--|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 419015 Type: WELL API Number: 077-10101 Status: PR Insp. Status: PR

Facility ID: 419019 Type: WELL API Number: 077-10102 Status: PR Insp. Status: PR

Facility ID: 419027 Type: WELL API Number: 077-10103 Status: PR Insp. Status: PR

Facility ID: 419043 Type: WELL API Number: 077-10104 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Berms | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 675204065 | Bruton 30-10 Pad | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108633 |