

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2017

Submitted Date:

03/28/2017

Document Number:

679700388**FIELD INSPECTION FORM**

Loc ID 414174 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10629Name of Operator: FIFTH CREEK ENERGY OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 420City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Sydney Smith		ssmith@fifthcreekenergy.com	Regulatory Analyst
Bill Irwin		birwin@fifthcreekenergy.com	VP Operations
Pesicka, Conor		conor.pesicka@state.co.us	COGCC Area Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413063	WELL	PR	03/24/2010	OW	123-30584	ELMER 8-31H	EI
448725	SPILL OR RELEASE	AC	03/22/2017		-	SPILL/RELEASE POINT	EI

General Comment:

COGCC Environmental Inspection followup to spill 448725. Corrective actions regarding unused equipment (frac tank stored) and stained soil around separator and wellhead noted on Inspection #6684901439 have been completed.

Inspected Facilities									
Facility ID:	413063	Type:	WELL	API Number:	123-30584	Status:	PR	Insp. Status:	EI
Facility ID:	448725	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	Soil stockpiled on liner on NW corner of pad, pending disposal			
Corrective Action				Date:

Spill/Remediation:

Comment: Spill remediation is in process. Targeted excavation around heater treater has occurred. Oily soil remains in excavation pending further removal or remediation.

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700391	Excavation around vertical southside	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110761
679700392	Excavation around vertical northside	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110762
679700393	Excavation around piping inside treater bldg	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110763
679700394	Oily soil stockpile in northwest corner of pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110764