

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2017

Submitted Date:

03/23/2017

Document Number:

670201427**FIELD INSPECTION FORM**

Loc ID 442832 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lind, Jennifer	(720) 508-8362	jlind@ursaresources.com	All Inspections
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
Kubeczko, Dave		dave.kubeczko@state.co.us	

General Comment:[Engineering group inspection to observe flowback process.](#)

Location Construction

Location ID: 442832 CDP: _____

Comment: Green completions equipment on location operated by LEC. Flowback of two wells occurring during inspection. Hydraulic stimulation of another well being performed by Haliburton. No propanant being used during stimulation. Flowback equipment consists of an inclined unit to separate junk from plug drill out, a vertical separator for each well being flowed back, and a horizontal unit for additional separation. Fluids are then piped to tanks and gas is routed to an enclosed flare until salable. Two enclosed flares on location for flowback and two additional combustors for production equipment. Temporary frac tanks on location to store produced water are connected to a pipeline system.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401241329	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106420