

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2017

Submitted Date:

03/23/2017

Document Number:

674901539

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76104
 Name of Operator: SAMSON RESOURCES COMPANY
 Address: 15 E 5TH ST STE 1000
 City: TULSA State: OK Zip: 74103

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Blanchard, Johnna	970-884-5085	jblanchard@samson.com	All SW Inspections

General Comment:

On March 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Samson Resources Pit Facility ID #115680. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115680 shall be administratively closed in the COGIS database after desktop review and this field inspection.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 115680 Lat: 37.051291 Long: -107.629850

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: [Location inspection conducted to determine physical existence of pit facility ID #115680.](#)

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
On March 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Samson Resources Pit Facility ID #115680. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115680 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pit.	hughesj	03/23/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401241490	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106623
674901540	Schofield Auto 31X #5-2 pump jack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106609
674901541	067-07488 well head. No surface indication of pit.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106610

