

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2017

Submitted Date:

03/23/2017

Document Number:

675204056**FIELD INSPECTION FORM**

Loc ID 312392 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 29470Name of Operator: FEES JR AND SON OIL & GAS* WALTER SAddress: 2516 FORESIGHT CIRCLE RM #10City: GRAND JUNCTION State: CO Zip: 81505**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fees, Walter		fwalter8@bresnan.net	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Lujan, Carlos		carlos.lujan@state.co.us	

General Comment:

Follow up to inspection Doc#675203369. Continue to monitor vegetation in tank containment per Rule 603.f.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Soil staining near Pump Jack. See attached photo.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Other	#		
Comment:	Stuffing box at wellhead is leaking condensate into wooden containment.		
Corrective Action:	Ensure good mechanical condition per Rule 605.d.		Date: 04/21/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:

Yes/No						
Comment:						
Corrective Action:					Date:	

Flaring:

Type					
Comment:					
Corrective Action:					Date:

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: Condensate present in wooden containment around wellhead.Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 04/21/2017

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401241584	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106722
675204059	Bar-X 28-3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106721