

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/24/2017

Submitted Date:

03/24/2017

Document Number:

672500478**FIELD INSPECTION FORM**
 Loc ID 444671 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445019	WELL	DG	03/23/2016		123-42853	CHESNUT 21Q-321	WO
445021	WELL	DG	05/02/2016		123-42855	CHESNUT 21T-221	WO
445022	WELL	DG	05/11/2016		123-42856	Chesnut 21Y-341	WO
445023	WELL	DG	05/07/2016		123-42857	CHESNUT 21Y-401	WO
445024	WELL	DG	04/14/2016		123-42858	CHESNUT 21T-301	WO
445025	WELL	DG	04/19/2016		123-42859	CHESNUT 21T-201	WO
445026	WELL	DG	04/25/2016		123-42860	CHESNUT 21T-321	WO

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

7

Comment:

OPEN TOP 500 BBL TANKS USED FOR FLOW BACK GROUNDED AND
SECONDARY CONTAINMENT

Corrective Action:

Date:

Type: Ancillary equipment

11

Comment:

FRESH WATER TANKS ON LOCATION

Corrective Action:

Date:

Type: Ancillary equipment

5

Comment:

MOBILE LIGHT TRAILERS W/LIGHTS POINTED TOWARD THE GROUND AND
TOWARD THE CENTER OF LOCATION

Corrective Action:

Date:

Type: Ancillary equipment

#

Comment:

BALES USED FOR SOUND MITIGATION ON THE SE SECTION OF LOCATION
STACKED APPROX 15'

Corrective Action:

Date:

Venting:

Yes/No

YES

Comment:

DRILL OUT

Corrective Action:

Date:

Flaring:

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 445019 Type: WELL API Number: 123-42853 Status: DG Insp. Status: WO

Workover

Comment: ENSIGN DRILLOUT

Corrective Action:

Date:

Completion

Operation: Drillout

Date Flowback: 03/24/2017

Contractor: COVENANT

Comment: 1 WELL DRILLED OUT 7 MORE TO COMPLETE

Corrective Action:

Date:

Facility ID: 445021 Type: WELL API Number: 123-42855 Status: DG Insp. Status: WO

Facility ID: 445022 Type: WELL API Number: 123-42856 Status: DG Insp. Status: WO

Facility ID: 445023 Type: WELL API Number: 123-42857 Status: DG Insp. Status: WO

Facility ID: 445024 Type: WELL API Number: 123-42858 Status: DG Insp. Status: WO

Facility ID: 445025 Type: WELL API Number: 123-42859 Status: DG Insp. Status: WO

Facility ID: 445026 Type: WELL API Number: 123-42860 Status: DG Insp. Status: WO

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Culverts	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401242956	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108362