

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2017

Submitted Date:

03/24/2017

Document Number:

675204062**FIELD INSPECTION FORM**Loc ID 334494 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274779	WELL	PR	06/24/2008	GW	077-08839	GUNDERSON FEDERAL 12-7	PR
276733	WELL	PR	05/30/2012	GW	077-08858	GUNDERSON 12-6	PR
276873	WELL	PR	02/01/2015	GW	077-08861	GUNDERSON 12-11	PR
276917	WELL	PR	08/01/2011	GW	077-08862	GUNDERSON 12-15	PR
277220	WELL	PR	08/01/2011	GW	077-08869	GUNDERSON FEDERAL 12-16	PR
277221	WELL	PR	02/01/2015	GW	077-08868	GUNDERSON 12-9	PR
277222	WELL	PR	08/18/2010	GW	077-08867	GUNDERSON 12-8	PR

General Comment:

Follow up to inspection Doc#675203849. CA's have not been met from previous inspection. See fence section of inspection form and attached photos.

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Wire fence is damaged. Potential wildlife or livestock hazard. See attached photos.		
Corrective Action:	Repair fence.	Date:	03/07/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,

Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	3	300 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: <u>274779</u>	Type: <u>WELL</u>	API Number: <u>077-08839</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>276733</u>	Type: <u>WELL</u>	API Number: <u>077-08858</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>276873</u>	Type: <u>WELL</u>	API Number: <u>077-08861</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>276917</u>	Type: <u>WELL</u>	API Number: <u>077-08862</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>277220</u>	Type: <u>WELL</u>	API Number: <u>077-08869</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>277221</u>	Type: <u>WELL</u>	API Number: <u>077-08868</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>277222</u>	Type: <u>WELL</u>	API Number: <u>077-08867</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401243149	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108635
675204066	Gunderson 12-10 Pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108632