

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2017

Submitted Date:

03/24/2017

Document Number:

675204064**FIELD INSPECTION FORM**Loc ID 418985 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419015	WELL	PR	05/06/2013	GW	077-10101	Bruton 30-16B	PR
419019	WELL	PR	07/09/2013	GW	077-10102	Bruton 30-10B	PR
419027	WELL	PR	05/06/2013	OG	077-10103	Bruton 30-08B	PR
419043	WELL	PR	04/29/2013	OG	077-10104	Bruton 30-06B	PR

General Comment:

Follow up to inspection Doc#675203849. CA's have not been met from previous inspection. See fence section of inspection form and attached photos.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wire fence is damaged. Potential wildlife or livestock hazard. See attached photo.		
Corrective Action:	Repair fence.	Date:	03/17/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: <u>419015</u>	Type: <u>WELL</u>	API Number: <u>077-10101</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>419019</u>	Type: <u>WELL</u>	API Number: <u>077-10102</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>419027</u>	Type: <u>WELL</u>	API Number: <u>077-10103</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>419043</u>	Type: <u>WELL</u>	API Number: <u>077-10104</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401243150	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108636
675204065	Bruton 30-10 Pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108633