

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2017

Submitted Date:

03/24/2017

Document Number:

678200647**FIELD INSPECTION FORM**

Loc ID 448384 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 49888Name of Operator: LARIO OIL & GAS COMPANYAddress: PO BOX 29City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Anderson, Christina		chris@lario.net	All Inspections
Eastwood, Blair	(720) 457-6567	blair@lario.net	Production Technician

General Comment:

[Environmental inspection related to the drilling pit. See pit sampling Corrective Action \(Date\).](#)

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action

Prior to backfilling the drilling pit (after the pit contents have dried sufficiently), collect a minimum of two discrete soil samples for laboratory analysis of BTEX and TPH to ensure compliance with Table 910-1 allowable levels. Provide the analytical results along with a sample location drawing to the NE EPS (rob.young@state.co.us). Contact NE EPS with if the pit contents have not dried sufficiently by the Corrective Action Date.

Date: 04/14/2017c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401243223	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108681
678200648	View west across drilling pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108678
678200649	View north across the middle of the drilling pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108679
678200650	View north across the west edge of the drilling pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108680