



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of eastern portion of the project area from the southeastern corner facing northward. Cut and fill slopes have been seeded and/or tackifier with mulch applied. Revegetation is occurring in portions of the outer disturbance areas with wheatgrasses and sandberg bluegrass (*Poa secunda*).



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of the western portion of the project area from the southwestern corner facing northward. Light green is tackifier and mulch on slope.



Photo 5: View of stormwater controls that appear to be functioning in the northern portion of the project area.



Photo 6: View of northeastern portion of the project area from the well pad entrance facing eastward.