



**Photo 1:** View of the project area from the southwestern corner facing center.



**Photo 2:** View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is largely comprised of grazed grasses such as intermediate wheatgrass (*Thinopyron intermedium*) and smooth brome (*Bromus inermis*).



**Photo 3: View of the southwestern portion of the project area from the southwestern corner facing northward.**



**Photo 4: View of the northern portion of the project area from the northeastern edge facing westward. Cobble run-down appears to be functioning at this time.**





**Photo 5: View of musk thistle rosettes within the eastern portion of the project area. Musk thistles were observed throughout the interim reclamation area.**



**Photo 6: View of small styrofoam debris within the eastern interim reclamation area. Several small pieces of debris such as styrofoam, black liner material, etc. are scattered around the interim reclamation area and need to be removed and properly disposed of.**





**Photo 7: View of stormwater controls that appear to be functioning in the western portion of the project area.**



**Photo 8: View of silt trap in the southeastern portion of the project area that appears to be functioning.**



**Photo 9: View of wattles in the eastern portion of the project area that are no longer functioning.**