



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*) and Intermediate wheatgrass (*Thinopyron intermedium*), and smooth brome (*Bromus inermis*).



Photo 3: View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4: View of musk thistles (*Carduus nutans*) within the southern portion of the interim reclamation area. Musk thistles are growing throughout the interim reclamation area and need treatment.



Photo 5: View of Canada thistles (*Carduus nutans*) within the southwestern portion of the project area.



Photo 6: View of cobble run-down in the southern portion of the project area that appears to be functioning.



Photo 7: View of wattles along access road that are filling with sediment and need maintenance.



Photo 8: Another view of wattles along the access road that are filled with sediment and need maintenance or replacement.