

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2017

Submitted Date:

04/03/2017

Document Number:

673404373**FIELD INSPECTION FORM**Loc ID 413754 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hewins, Grant		ghewins@sandridgeenergy.com	
Laird, Spence		slaird@sandridgeenergy.com	
James, Michael	405-519-6634	mjames@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412904	WELL	PR	04/15/2014	OW	057-06499	HEBRON 02-07H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 405-429-5974

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Tubing and portable containment stored at wellhead.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 08/03/2017

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: Clean-up of historical spill at wellhead is ongoing in accordance with spill report document number 401201164.

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 412904	Type: WELL	API Number: 057-06499	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pumping.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Gravel	Pass			
Compaction	Pass					
Silt Fences	Fail					Silt fence falling down.
		Ditches	Pass			
Berms	Pass					Perimeter berm made of cuttings.
Ditches	Pass					
Culverts	Pass					
Gravel	Pass					
		Culverts	Pass			

Comment: [Perimeter berm made of cuttings in accordance with Sandridge Waste Management Plan approved via sundry document number 401062567.](#)
[Silt fence on perimeter of berm is falling down in numerous spots and is no longer an effective BMP.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.](#)

Date: 05/03/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404379	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116004