

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2016

Submitted Date:

03/25/2017

Document Number:

678200651**FIELD INSPECTION FORM**

Loc ID 316949 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	
Fritzler, Gene		gfritzler12@gmail.com	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107655	PIT	AC			-	WEST FORK UNIT 17	EI

General Comment:

Environmental inspection to document progress related to Rem #9126. Pit berms have been improved, the former produced water outlet pipe has been removed. Soil sample results from the downgradient salt impacted flowpath shall be provided to the COGCC by April 21, 2017. Groundwater data from the two proposed sample locations shall be provided to the COGCC by April 21, 2017. Provide a schedule for the surface reclamation of the salt impacted flow path to the COGCC by April 21, 2017.

Inspected Facilities									
Facility ID:	107655	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 107655Lat: 39.779403Long: -103.591529Reference Point: Other: Length: 165Width: 90**Lining:**Liner Type: Liner Condition: Comment: Pit berms have been raised/improved, the two pits are visible on COGIS are connected, dimensions indicate overall configuration.Corrective Action: Date: g**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401243500	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108932
678200652	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108931