

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2017

Submitted Date:

03/29/2017

Document Number:

666803065**FIELD INSPECTION FORM**
 Loc ID 335309 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260227	WELL	PR	05/25/2001	GW	045-07838	CLOUGH RWF 21-28	PR
271632	WELL	PR	03/17/2004	GW	045-09924	CLOUGH RWF 421-28	PR
271635	WELL	PR	04/20/2005	GW	045-09921	CLOUGH RWF 521-28	PR
272208	WELL	PR	04/24/2005	GW	045-10039	CLOUGH RWF 411-28	PR
272210	WELL	PR	04/24/2005	GW	045-10040	CLOUGH RWF 511-28	PR

General Comment:[Facilities on location ID 311583](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

5

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

0

Comment:

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: <u>260227</u>	Type: <u>WELL</u>	API Number: <u>045-07838</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>271632</u>	Type: <u>WELL</u>	API Number: <u>045-09924</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>271635</u>	Type: <u>WELL</u>	API Number: <u>045-09921</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>272208</u>	Type: <u>WELL</u>	API Number: <u>045-10039</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:		Date:		
Facility ID: <u>272210</u>	Type: <u>WELL</u>	API Number: <u>045-10040</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Plunger lift</u>				
Corrective Action:		Date:		

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
		Compaction	Pass			
Slope Roughening	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401246902	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4112000