



photo 1: Facing southeast along the access road.



photo 2: Gravel remains along the access road.



photo 3: Facing southeast toward the location.



photo 4: Gravel remains in areas of the location.



photo 5: Facing along the west fill slope.



photo 6: There is an erosion channel off the south side of the location.



photo 7: Facing toward the southeast cut slope.



photo 8: South side of the location facing north.



photo 9: Facing southeast along the cut slope of the location.



photo 10: Facing southwest toward the location.