

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/30/2017

Submitted Date:

04/06/2017

Document Number:

674901592**FIELD INSPECTION FORM**
 Loc ID 325454 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspections@sginterests.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115679	PIT		09/23/1999		-	MCELVAIN 3	

General Comment:

On March 30, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #115679. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115679 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType: Lined: Pit ID: 115679 Lat: 37.018961 Long: -107.561908Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Location inspection conducted to determine physical existence of pit facility ID #115679.Corrective Action Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **COGCC Comments**

Comment	User	Date
<u>On March 30, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #115679. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115679 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.</u>	hughesj	04/06/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901593	Location photo looking SE.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117775
674901594	Location photo looking SW.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117776
674901595	Location photo looking NE.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117777