

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

674703799**FIELD INSPECTION FORM**

Loc ID 335800 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name         | Phone        | Email                        | Comment                                 |
|----------------------|--------------|------------------------------|---|
| Inspections, General | 970-285-2665 | cogcc.inspections@encana.com | <a href="#">EnCana Inspection email</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 277115      | WELL | PR     | 01/05/2006  | GW         | 045-10604 | N.PARACHUTE WF14D A15 596 | PR          |
| 428147      | PIT  | AC     | 03/12/2012  |            | -         | WEST FORK A-15 596        | AC          |

**General Comment:**

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action | L      | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | BATTERY    |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

**Good Housekeeping:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | TRASH |       |  |
| Comment:           |       |       |  |
| Corrective Action: |       | Date: |  |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | PIT      |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                       |     |  |                 |
|-----------------------|-----|--|-----------------|
| Type: Bird Protectors | # 1 |  | corrective date |
| Comment:              |     |  |                 |

|                                   |                                       |       |  |
|-----------------------------------|---------------------------------------|-------|--|
| Corrective Action:                |                                       | Date: |  |
| Type: Plunger Lift                | # 1                                   |       |  |
| Comment:                          |                                       |       |  |
| Corrective Action:                |                                       | Date: |  |
| Type: Gas Meter Run               | # 2                                   |       |  |
| Comment:                          |                                       |       |  |
| Corrective Action:                |                                       | Date: |  |
| Type: Horizontal Heated Separator | # 1                                   |       |  |
| Comment:                          |                                       |       |  |
| Corrective Action:                |                                       | Date: |  |
| Type: Ancillary equipment         | # 1                                   |       |  |
| Comment:                          | Chemical container at gas meter shed. |       |  |
| Corrective Action:                |                                       | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |                                |                       |            |                  |               |            |                  |
|----------------------|--------------------------------|-----------------------|------------|------------------|---------------|------------|------------------|
| Facility ID: 277115  | Type: WELL                     | API Number: 045-10604 | Status: PR | Insp. Status: PR |               |            |                  |
| Producing Well       |                                |                       |            |                  |               |            |                  |
| Comment:             | Producing well on plunger lift |                       |            |                  |               |            |                  |
| Corrective Action:   |                                |                       |            | Date:            |               |            |                  |
| Facility ID: 428147  |                                |                       |            | Type: PIT        | API Number: - | Status: AC | Insp. Status: AC |

### Reclamation - Storm Water - Pit

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
|                  |                 | Gravel                  | Pass                  |  |                          |         |
| Berms            | Pass            |                         |                       |  |                          |         |
| Seeding          | Pass            |                         |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
| Compaction       | Pass            |                         |                       |  |                          |         |
| Check Dams       | Pass            |                         |                       |  |                          |         |
|                  |                 | Ditches                 | Pass                  |  |                          |         |
|                  |                 | Culverts                | Pass                  |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
| Gravel           | Pass            |                         |                       |  |                          |         |
| Ditches          | Pass            |                         |                       |  |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:  Lined: YES Pit ID: 42814Z Lat: 39.621792 Long: -108.148903

Reference Point:  Other:  Length:  Width:

**Lining:**

Liner Type:  Liner Condition: Adequate

Comment: Corrective Action Date: g**Fencing:**

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment: Corrective Action Date: **Netting:**

Netting Type: Fence/Net Combo Netting Condition: Good

Comment: Corrective Action Date: 

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Corrective Action Date: 

| Permit: | Facility ID | Permit Num | Expiration Date      |
|---------|-------------|------------|----------------------|
|         | 425200      | 1642063    | <input type="text"/> |

Inspector Name: LONGWORTH, MIKE

|             |                 |          |  |
|-------------|-----------------|----------|--|
|             | 425199          | 1642062  |  |
|             | 428147          | 2222736  |  |
| Monitoring: | Monitoring Type | Comment` |  |
|             | Chain           |          |  |

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 674703800    | A15 596 photo from entrance | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118191</a> |