

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

674703803

FIELD INSPECTION FORM

Loc ID 335593 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280958	WELL	PR	05/03/2006	GW	045-11384	N.PARACHUTE WF07B D23A 596	PR
281017	WELL	PR	08/25/2007	GW	045-11385	N.PARACHUTE WF 10D D23A 596	PR
281018	WELL	PR	10/31/2005	GW	045-11386	N.PARACHUTE WF 15B D23A 596	PR
281019	WELL	PR	02/01/2011	GW	045-11387	N. PARACHUTE WF14B D23A 596	PR
281020	WELL	PR	11/01/2006	GW	045-11388	N. PARACHUTE WF10B D23A 596	PR
281021	WELL	PR	05/30/2006	GW	045-11389	N.PARACHUTE WF01B D23A 596	PR
281022	WELL	PR	06/19/2006	GW	045-11390	N.PARACHUTE WF02B D23A 596	PR
281023	WELL	PR	05/30/2006	GW	045-11391	N.PARACHUTE WF03B D23A 596	PR

General Comment:

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	800-791-7691		
Corrective Action:			Date:
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 8		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical containers at gas meters		
Corrective Action:			Date:

Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	280958	Type:	WELL	API Number:	045-11384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281017	Type:	WELL	API Number:	045-11385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281018	Type:	WELL	API Number:	045-11386	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281019	Type:	WELL	API Number:	045-11387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281020	Type:	WELL	API Number:	045-11388	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281021	Type:	WELL	API Number:	045-11389	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281022	Type:	WELL	API Number:	045-11390	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				
Facility ID:	281023	Type:	WELL	API Number:	045-11391	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:					Date:				

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Check Dams	Pass					
Mulching	Pass					
Gravel	Pass					
		Ditches	Pass			
		Gravel	Pass			
Berms	Pass					
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703804	D23A 596 photos from well heads	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118193