

Inspection Photos
Location Name: Futhey 3
API: 05-013-06046



Stained soil under leaking pipe connection on separator.



Close-up of stained soil under separator

Inspection Photos
Location Name: Futhey 3
API: 05-013-06046



Stained soil at base of west oil tank
Taken from east looking west.



Stained soil at base of east oil tank.
Taken from between tanks looking east.

Inspection Photos
Location Name: Futhey 3
API: 05-013-06046



**Stained soil at base of east oil tank.
Taken from east looking west.**



**Stained soil at base of both oil tanks.
Taken from east looking west.**